Website ROMSHI.COM | +7(918)0110234 in Whats App, Telergam SUPPLIER OF DIODE STACKS, EPILATION LASERS AND EQUIPMENT

LASER BAR DVS-1012AI



In most cases, the handle malfunction is due to the fact that there are no visual outbreaks and sensations on the skin.Damage is often visible through the observation glass.



site WWW.ROMSHI.COM

Laser not working? Diode stack may be faulty. Scan for repair options on www.romshi.com.