


LASER MODULE DVS-L-1010BAI



Frequent malfunction of the laser handle - the laser stops issuing impulses, there are no sensations. Often the problem can be seen through the observation window.



Find spare diode components in seconds - scan for romshi.com.