
Website ROMSHI.COM | +7(918)0110234 in Whats App, Telergam SUPPLIER OF DIODE STACKS, EPILATION LASERS AND EQUIPMENT

DIODE STACK LST-1006BAI



Often, the diode laser has a problem: flashes do not occur, there is no tingling either. Often it is enough to look out the window of the pen to see the problem.



site WWW.ROMSHI.COM

Scan the QR to access repair knowledge and trusted diode part suppliers.