
Website ROMSHI.COM | +7(918)0110234 in Whats App, Telergam SUPPLIER OF DIODE STACKS, EPILATION LASERS AND EQUIPMENT

DIODE ASSEMBLY GTHM-150



A common breakdown of the handle is that there is a loss of flashes and sensations. Often the problem can be seen through the observation window.



site WWW.ROMSHI.COM

Diode laser not working? Scan to find which part to replace via romshi.com.