
Website ROMSHI.COM | +7(918)0110234 in Whats App, Telergam SUPPLIER OF DIODE STACKS, EPILATION LASERS AND EQUIPMENT

DIODE MATRIX GTHM-300



Often, the diode laser handle fails: flashes do not occur, there is no tingling either. Often it is enough to look out the window of the pen to see the problem.



site WWW.ROMSHI.COM

For expert tips on diode stack repair, scan the QR and go to www.romshi.com.