
Website ROMSHI.COM | +7(918)0110234 in Whats App, Telergam SUPPLIER OF DIODE STACKS, EPILATION LASERS AND EQUIPMENT

DIODE MATRIX DVS-3217AS



Frequent fault of the laser handle - flashes disappear and there is no tingling. Often the problem is determined visually through the window on the handle.



site WWW.ROMSHI.COM

Is your laser still? Scan the QR to find a solution at www.romshi.com.