



REPLACEMENT DIODE MODULE FOR HANDPIECE OF DIODE LASER HAIR REMOVAL



A common breakdown of the handle is that the laser does not emit flash and does not cause sensations. Often the problem can be seen through the observation window.



site WWW.ROMSHI.COM

Laser equipment not functioning? Scan the QR code and discover repair resources on www.romshi.com.