
EXTRA DIODE STACK FOR DIODE LASER HAIR REMOVAL HANDPIECE



Often, the diode laser handle fails: the impulses do not pass, the patient does not feel tingling. Often the problem is determined visually through the window on the handle.



site WWW.ROMSHI.COM

Laser failure? Check your diode stack. Repair advice and parts at www.romshi.com via QR code.