Website ROMSHI.COM | +7(918)0110234 in Whats App, Telergam SUPPLIER OF DIODE STACKS, EPILATION LASERS AND EQUIPMENT

SPARE DIODE UNIT FOR LASER HAIR REMOVAL DEVICE



One of the typical problems of the diode laser is that the outbreaks do not occur, there is no tingling either. Often the problem can be seen through the observation window.



site WWW.ROMSHI.COM

When laser hair removal fails, scan QR for help at www.romshi.com-usually a diode issue.