
## Website ROMSHI.COM | +7(918)0110234 in Whats App, Telergam SUPPLIER OF DIODE STACKS, EPILATION LASERS AND EQUIPMENT

## REPLACEMENT DIODE UNIT FOR DIODE LASER HAIR REMOVAL APPARATUS



Often, the diode laser handle fails: the laser ceases to give out impulses, there are no sensations. Sometimes it can be recognized visually by looking out the window.



site WWW.ROMSHI.COM

Laser performance dropped? A bad diode stack may be the cause.

Visit www.romshi.com via QR scan.