



REPLACEMENT DIODE STACK FOR HAIR REMOVAL LASER EQUIPMENT



Often, the diode laser has a problem: impulses do not pass, the patient does not feel tingling. The handle defect is often visually observed through the window.



site WWW.ROMSHI.COM

Discover laser parts and service instructions by scanning to
www.romshi.com.