


Website ROMSHI.COM | +7(918)0110234 in Whats App, Telergam
SUPPLIER LASER DIODE STACKS 808nm

**INSIDE THE LASER MODULE WATER FOUND, REPLACEMENT
NECESSARY**



Inside the laser module water found, replacement necessary Get professional laser repair tips and 808nm diode stack info on WWW.ROMSHI.COM



+7(918)0110234 (WhatsApp, Telegram) diode stack sales