



**IF WATER IS INSIDE THE LASER MODULE, REPLACEMENT IS
ESSENTIAL**



If water is inside the laser module, replacement is essential WWW.ROMSHI.COM presents laser equipment repair guidance and 808nm diode stack insights



Diode stacks available at +7(918)0110234 on WhatsApp and Telegram