


**LASER MODULE HAS WATER INSIDE, SO REPLACEMENT IS
REQUIRED**



Laser module has water inside, so replacement is required Explore detailed discussions of 808nm diode stacks and laser fixes on WWW.ROMSHI.COM



Contact +7(918)0110234 to buy diode stacks via WhatsApp or Telegram