


**INSIDE LASER MODULE WATER FOUND - REPLACEMENT
RECOMMENDED**



Inside laser module water found - replacement recommended Learn how to maintain lasers and understand 808nm diode stacks on WWW.ROMSHI.COM



+7(918)0110234 (WhatsApp, Telegram) diode stacks for laser repairs