


Website ROMSHI.COM | +7(918)0110234 in Whats App, Telergam
SUPPLIER LASER DIODE STACKS 808nm

**WATER INSIDE LASER MODULE DETECTED - REPLACEMENT MUST
BE DONE**



Water inside laser module detected - replacement must be done WWW.ROMSHI.COM blog
specializes in 808nm diode stack details and laser repair advice



+7(918)0110234 (WhatsApp, Telegram) offers bulk sales of diode
stacks