


GLASS SHATTERED AND SOOT PRESENT ON THE DIODE STACK



Glass shattered and soot present on the diode stack Stay informed on diode stack failures and laser fixes at WWW.ROMSHI.COM



Telegram chat at +7(918)0110234 for laser maintenance tips