
Website ROMSHI.COM | +7(918)0110234 in Whats App, Telergam SUPPLIER OF DIODE STACKS LST, DVS 808nm

PRECISION LASER REPAIR - DIODE STACK SWAP



Signs of a malfunction of a diode pen



Replacing the stack and laser bar in the handle of the epilation diode laser - high -quality turnkey repair. Site WWW.ROMSHI.COM