

ELIMINATION OF MALFUNCTIONS IN THE WORKING PART OF THE LASER



Replacing the stacks in the manipulas of 808nm with a guarantee.



site WWW.ROMSHI.COM

Scan the QR for help diagnosing your laser-likely the diode stack.

Info at www.romshi.com.