


SEARCH FOR FAULTS IN THE LASER HANDLE



We will select and set the stack 808nm of the desired power.



site WWW.ROMSHI.COM

Is your hair laser underperforming? The QR code takes you to www.romshi.com for diode-related fixes.