


DIODE MATRIX DVS-ML-3255BAS



Dot in the work of the diode laser handle is expressed as follows: the flashes stop and the sensation of tingling disappears and disappears. Often the problem is determined visually through the window on the handle.



site WWW.ROMSHI.COM

Hair laser repairs simplified - scan QR for parts from
www.romshi.com.