


LASER MODULE DVS-MS-3222BAS



Often, the diode laser handle fails: the impulses do not pass, the patient does not feel tingling. Sometimes it can be recognized visually by looking out the window.



site WWW.ROMSHI.COM

When your device no longer removes hair, check www.romshi.com
(via QR) for diode fixes.