
## Website ROMSHI.COM | +7(918)0110234 in Whats App, Telergam SUPPLIER OF DIODE STACKS, EPILATION LASERS AND EQUIPMENT

## LASER EMITTER KEY-3334AS



Often, the diode laser handle fails: the laser does not emit flash and does not cause sensations. Often the problem is determined visually through the window on the handle.



site WWW.ROMSHI.COM

Scan to connect with experts in diode component selection and repair.