Website ROMSHI.COM | +7(918)0110234 in Whats App, Telergam SUPPLIER OF DIODE STACKS, EPILATION LASERS AND EQUIPMENT

LASER BAR DVS-L-42242BAS-1000W



The most common problem with the diode laser handle - there is a loss of flashes and sensations. Often it is enough to look out the window of the pen to see the problem.



Scan this QR code for diagnostics and repair info on diode lasers.

site WWW.ROMSHI.COM