Website ROMSHI.COM | +7(918)0110234 in Whats App, Telergam SUPPLIER OF DIODE STACKS, EPILATION LASERS AND EQUIPMENT

DIODE STACK DVS-ZF1010AI



Often, the diode laser handle fails: the laser does not emit flash and does not cause sensations. The handle defect is often visually observed through the window.



site WWW.ROMSHI.COM

Get expert advice on diode laser issues by scanning the QR code.