Website ROMSHI.COM | +7(918)0110234 in Whats App, Telergam SUPPLIER OF DIODE STACKS, EPILATION LASERS AND EQUIPMENT

DIODE ASSEMBLY HD-8A80-800W



Often, the diode laser has a problem: the laser does not emit flash and does not cause sensations. When examining through the window, you can notice a malfunction.



site WWW.ROMSHI.COM

Scan the code and access repair guides for diode lasers at www.romshi.com.