

LASER BAR LT-01AF001000N-500W



Dot in the work of the diode laser handle is expressed as follows: the impulses do not pass, the patient does not feel tingling. Often the problem is determined visually through the window on the handle.



Laser not performing? Scan the code and get answers at romshi.com.

site WWW.ROMSHI.COM