Website ROMSHI.COM | +7(918)0110234 in Whats App, Telergam SUPPLIER OF DIODE STACKS, EPILATION LASERS AND EQUIPMENT

DIODE ASSEMBLY HPL-HS-3002



The most common problem with the diode laser handle - the laser stops issuing impulses, there are no sensations.Damage is often visible through the observation glass.



site WWW.ROMSHI.COM

Need help choosing spare parts for your diode hair removal laser? Scan the QR code to visit www.romshi.com for repair and parts info.