

LASER EMITTER HR11600EY1596



One of the typical problems of the diode laser is that the outbreaks stop and the sensation of tingling disappears. Damage is often visible through the observation glass.



If your laser unit fails, the diode stack might be the problem. Learn more at www.romshi.com via QR code.

site WWW.ROMSHI.COM