Website ROMSHI.COM | +7(918)0110234 in Whats App, Telergam SUPPLIER OF DIODE STACKS, EPILATION LASERS AND EQUIPMENT

DIODE ASSEMBLY HR10800DL1634



Often, the diode laser handle fails: flashes do not occur, there is no tingling either. Sometimes it can be recognized visually by looking out the window.



site WWW.ROMSHI.COM

Unsure what diode spare you need? www.romshi.com has answers. Scan the QR to see.