Website ROMSHI.COM | +7(918)0110234 in Whats App, Telergam SUPPLIER OF DIODE STACKS, EPILATION LASERS AND EQUIPMENT

DIODE STACK GTHM-250



Often, the diode laser has a problem: impulses do not pass, the patient does not feel tingling. The breakdown is often noticeable when examining the handle.



site WWW.ROMSHI.COM

Scan the QR code to visit www.romshi.com for spare diode parts and repair guidance.