

DIODE MATRIX GTHM-350



Drages in the work of the diode laser handle are expressed as follows: there is a loss of flashes and sensations. The breakdown is often noticeable when examining the handle.



Hair not being removed? You may need a new diode stack. Scan QR for www.romshi.com.

site WWW.ROMSHI.COM