Website ROMSHI.COM | +7(918)0110234 in Whats App, Telergam SUPPLIER OF DIODE STACKS, EPILATION LASERS AND EQUIPMENT

LASER BAR DVS-F1012BAI



Often, the diode laser handle fails: there is a loss of flashes and sensations. Often it is enough to look out the window of the pen to see the problem.



site WWW.ROMSHI.COM

Laser failure? Check your diode stack. Repair advice and parts at www.romshi.com via QR code.