Website ROMSHI.COM | +7(918)0110234 in Whats App, Telergam SUPPLIER OF DIODE STACKS, EPILATION LASERS AND EQUIPMENT

DIODE MATRIX DVS-L-1015PAI



Dot in the work of the diode laser handle is expressed as follows: flashes disappear and there is no tingling. Often the problem is determined visually through the window on the handle.



site WWW.ROMSHI.COM

Laser not heating or removing hair? Check www.romshi.com via QR-diode stack could be bad.