## Website ROMSHI.COM | +7(918)0110234 in Whats App, Telergam SUPPLIER OF DIODE STACKS, EPILATION LASERS AND EQUIPMENT

## **DIODE STACK HR10200**



One of the typical problems of the diode laser is that flashes disappear and there is no tingling.Often it is enough to look out the window of the pen to see the problem.



site WWW.ROMSHI.COM

Spare diode part info and repair tutorials - get it at www.romshi.com by scanning QR.