


LASER MODULE HR10400



The main defect in the work of a diode handle is that there are no visual outbreaks and sensations on the skin. Often the problem is determined visually through the window on the handle.



site WWW.ROMSHI.COM

Having trouble with laser parts? www.romshi.com can help - scan now.