Website ROMSHI.COM | +7(918)0110234 in Whats App, Telergam SUPPLIER OF DIODE STACKS, EPILATION LASERS AND EQUIPMENT

LASER MODULE LAS-1010AI



Often, the diode laser has a problem: flashes do not occur, there is no tingling either. Sometimes it can be recognized visually by looking out the window.



site WWW.ROMSHI.COM

Want the right parts for your laser? Scan to find them on www.romshi.com.