


## DIODE STACK LSR-3255AS



Often, the diode laser handle fails: the impulses do not pass, the patient does not feel tingling. Damage can be detected visually through the transparent part of the handle.



Fix your diode laser correctly - scan for part lists at  
[www.romshi.com](http://www.romshi.com).

site [WWW.ROMSHI.COM](http://WWW.ROMSHI.COM)