


## **LASER MODULE 02B-2303-0604**



Often, the diode laser handle fails: no light impulses are visible, there is no contact with the skin. Often the problem is determined visually through the window on the handle.



Scan the QR code for expert-selected parts and laser repair tips at  
[romshi.com](http://romshi.com).