


LASER MODULE LST-MS-1006BAI



The main defect in the work of the diode handle is that the outbreaks do not occur, there is no tingling either. Through the observation window, the cause of the breakdown is often visible.



Diode laser acting up? Scan for diagnostics and parts info at romshi.com.