


LASER EMITTER LST-1007AI



The most common problem with the diode laser handle is that flashes disappear and there is no tingling. Often the problem is determined visually through the window on the handle.



Is your laser failing? Find expert help at www.romshi.com through the QR code.