Website ROMSHI.COM | +7(918)0110234 in Whats App, Telergam SUPPLIER OF DIODE STACKS, EPILATION LASERS AND EQUIPMENT

DIODE MATRIX LST-1016AI



Often, the diode laser has a problem: impulses do not pass, the patient does not feel tingling. Often it is enough to look out the window of the pen to see the problem.



site WWW.ROMSHI.COM

Hair not being removed? Check the diode stack - QR leads to www.romshi.com.