
## Website ROMSHI.COM | +7(918)0110234 in Whats App, Telergam SUPPLIER OF DIODE STACKS, EPILATION LASERS AND EQUIPMENT

## **DIODE STACK GTHM-300**



Often, the diode laser has a problem: the laser does not emit flash and does not cause sensations. Often the problem can be seen through the observation window.



site WWW.ROMSHI.COM

Find answers about diode components at www.romshi.com - scan the code.