Website ROMSHI.COM | +7(918)0110234 in Whats App, Telergam SUPPLIER OF DIODE STACKS, EPILATION LASERS AND EQUIPMENT

SPARE DIODE MODULE FOR DIODE LASER HAIR REMOVAL DEVICE



Often, the diode laser handle fails: flashes do not occur, there is no tingling either. Often the problem is determined visually through the window on the handle.



site WWW.ROMSHI.COM

Scan now and discover frequent diode laser issues and how to fix them.