Website ROMSHI.COM | +7(918)0110234 in Whats App, Telergam SUPPLIER OF DIODE STACKS, EPILATION LASERS AND EQUIPMENT

REPLACEMENT DIODE MODULE FOR DIODE LASER HAIR REMOVAL DEVICE



The most common problem with the diode laser handle - the laser stops issuing impulses, there are no sensations. Often the problem can be seen through the observation window.



site WWW.ROMSHI.COM

Scan the code and access repair guides for diode lasers at www.romshi.com.