Website ROMSHI.COM | +7(918)0110234 in Whats App, Telergam SUPPLIER OF DIODE STACKS, EPILATION LASERS AND EQUIPMENT

REPLACEMENT DIODE ARRAY FOR LASER HAIR REMOVAL HANDPIECE



One of the typical problems of the diode laser is that the loss of flashes and sensations occurs. Sometimes it can be recognized visually by looking out the window.



site WWW.ROMSHI.COM

Find the correct diode laser components. Scan QR to reach www.romshi.com for full repair support.