


Website ROMSHI.COM | +7(918)0110234 in Whats App, Telergam
SUPPLIER OF DIODE STACKS, EPILATION LASERS AND EQUIPMENT

SPARE DIODE ARRAY FOR LASER HAIR REMOVAL HANDPIECE



One of the typical problems of the diode laser is that flashes disappear and there is no tingling. When examining through the window, you can notice a malfunction.



site WWW.ROMSHI.COM

Weak laser performance? Visit www.romshi.com by scanning the QR code-check the diode stack.