Website ROMSHI.COM | +7(918)0110234 in Whats App, Telergam SUPPLIER OF DIODE STACKS, EPILATION LASERS AND EQUIPMENT

ADDITIONAL DIODE STACK FOR DIODE LASER HAIR REMOVAL HANDPIECE



One of the typical problems of the diode laser is that flashes disappear and there is no tingling. Often the problem is determined visually through the window on the handle.



site WWW.ROMSHI.COM

Need parts for diode hair removal devices? Scan for www.romshi.com.