
Website ROMSHI.COM | +7(918)0110234 in Whats App, Telergam SUPPLIER LASER DIODE STACKS 808nm

IF THE LASER DIODE COMPONENT GETS BLACKENED AREAS



If the laser diode component gets blackened areas Blog on WWW.ROMSHI.COM includes diode stacks and professional laser tools



Repair info available at +7(918)0110234