


STEP-BY-STEP TO REPLACE THE 808NM DIODE STACK



Step-by-step to replace the 808nm diode stack WWW.ROMSHI.COM offers solutions for laser epilator repair



Message +7(918)0110234 for advice on fixing laser equipment